

Doc. N.° 1SDH000719R0603 - L4099

SACE Tmax XT

MOD - Comando a motore diretto cablato XT1-XT3
MOD - Wired direct-acting motor operator XT1-XT3
MOD - Motorantrieb mit Direktwirkung, verdrahtet XT1-XT3
MOD - Commande par moteur a action directe câblé XT1-XT3
MOD - Mando a motor de accion directa cableado XT1-XT3

XT1-XT3






XT1	2	2	4	2	/	/	1
XT3	2	2	4	/	1	1	1

R1= Resistore esterno addizionale per comando a motore diretto alimentato a 480/525Vca.
R1= Additional external direct-acting motor operator resistor powered at 480/525 Vac.
R1= Zusätzlicher externer Widerstand für Motorantrieb mit Direktwirkung mit Speisung bei 480/525 V AC.
R1= Résistance extérieure supplémentaire à commande par moteur a action direct alimentée à 480/525Vca.
R1= Resistor externo adicional para mando a motor de accion directaalimentado a 480/525Vca.

Power and productivity
for a better world™


A

XT1-XT3 / F-P




B

XT1-XT3 / F-P




C

XT1-XT3 / F-P




D

XT1-XT3 / F-P




E

XT1-XT3 / F-P




F

XT1 / F-P




G

XT3 / F-P




H

XT1 / F




I

XT1 / F




J

XT3 / F




K

XT3 / F




L

XT1 / F




M

XT3 / F




N

XT1-XT3 / P




O

XT1-XT3 / P




P


XT1-XT3 / P




Q




R




S



T




U




V

XT1-XT3 / F-P




W

XT1-XT3 / F-P



X

XT1-XT3 / F-P



For more information please contact:

ABB S.p.A.
ABB SACE Division
Via Baioni, 35
24123 Bergamo - Italy
Phone: +39 035 395 111
Fax: +39 035 395 306 - 433

www.abb.com

Power and productivity
for a better world™