


JROYM04



1h

99
HIC






48h




K21
x2
>0.06m²



v010
08.02.2021
A. P.
[cm]


BENITO
-Play









[cm]





[cm]




[cm]



1h






127245
x2




127246
x1

K1, K2









996227
x2




122105
x2



1x	12e005
1x	12e029
1x	12e044
1x	122107
1x	b440
1x	V001

10x	8x50sxi












2x 8x50sxi



1x 12e005







BENITO
 C/Leida 10
 08500 Vic
 Barcelona Spain
 T +34 938 521 000
 info@benito.com
 www.benito.com

Conforme a las exigencias de seguridad
 Conform aux exigences de sécurité
 According to safety requirements

Ref: _____ EN 1176-1
 Edad/Äge/Age _____ EN 1176
 Ukur/ouk/Utilisateurs / Users _____

01 02 03 04 05 06 07 08 09 10 11 12 16 17

Part No:
000000-00000

000000-00000