





# JPVA02




[cm]





v011/05.08.19




**BENITO**





[cm]








	SD
M10x120 x38	
<b>NOT INCLUDED</b>	



[cm]



0163A  
x1



0163B  
x1



0163C  
x1



0163D  
x1



0163E  
x1




0163F  
x1



0163G  
x1




0163H  
x1




0163I  
x1




012101  
x1



012100  
x1



015116  
x1



011121  
x1




011127  
x1




011122  
x1




011154  
x1



011226  
x1



011229  
x1



011232  
x1



011124  
x1



011139  
x1




011130  
x1




011132  
x4




011157  
x1




011143  
x2




011119  
x2



994146  
x1



i27-5  
x1











i28-5  
x1

<b>SD</b>	<b>SD</b>	<b>SB</b>
b231 x9	b219-2 x2	P78-3 x2


ST/INOX		PLYWOOD	
2x	E1	4x	CE1
1x	E12	1x	CE3
1x	E13	1x	CE4
1x	E34***	1x	CE6
	E37**	1x	CE11
1x	E93	1x	CE17
		1x	CE27
		1x	PS8
		1x	PS9
		1x	PS11
		1x	PS19 (S1) PS41 (S6)
		2x	PS58

\*\*SD  
\*\*\*SB, SD












1x CE17




1x CE6




1x CE27







4x CE1



1x CE11




1x CE4




2x PS19  
S1

2x PS41  
S6

[cm]




2x PS58




1x E12



1



2



1x CE3



1x E93

